

	Appliance Details						Inspection Details								
	Location	Appliance Type	Make	Model	Flue Type FL/ OF RS-BF RS-FF	Yes / No / NA	Appliance Inspected Yes/No	Operating pressure in mbars or heat input kW/h	Safety device(s) correct operation Yes /No /NA	Ventilation provision satisfactory Yes/No	Visual condition of flue and termination satisfactory Yes/No/NA	Checks Pass / Fail /	Appliance serviced Yes / No	Appliance safe to use Yes / No	
1	Cupboard	Combi Boiler	Vaillant	ECOTEC PRO 24	RS-FF	Yes	Yes	22.06 kW/h	Yes	Yes	Yes	Pass	No	Yes	
2	Kitchen	Hob	Lamona	Unknown	FL	Yes	Yes	8.05 kW/h	Yes	Yes	Yes	Pass	No	Yes	
3															
4															
5															
6															

Defects Identified	Remedial Action Taken	Warning Notice issued	Combustion Analysis Readings								
Delects identified		Yes (serial) / No	1st Reading/Min/Low			2nd Reading/Max/High			3rd Reading/Ign/Other		
			CO	CO2	Ratio	СО	CO2	Ratio	СО	CO2	Ratio
1 CO readings are high	Book in a gas/air adjustment ASAP.		182	4.7	.0039	182	4.7	.0039	182	4.7	.0039
2			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3											
4											
5											

6

Sign-off Flue Types Key **Final Checks** FL - Flueless Gas Tightness Test initial value: 20 mbar TT final value: 20 mbar This Safety record is issued by: Signed OF - Open Flue Yes Satisfactory gas tightness test Yes/No/NA RS-BF - Room sealed balanced flue Gas installation pipework satisfactory visual inspection Yes/No Yes RS-FF - Room sealed fan flue Emergency Control accessible Yes/No Yes Gas Operative: Darren Bryan NEXT SAFETY CHECK DUE Main Protective Equipotential Bonding satisfactory Yes/No No Operative ID No: 5079306 Date: 26 April 2022 **BEFORE 26 April 2023** CO alarm present? No CO alarm working? n/a In date? n/a Received by: Signed 17/all Smoke alarm(s) working? Smoke alarm(s) present? Yes Yes This inspection is for gas safety purposes only in accordance with the Gas Safety (Installation and Use) Regulations. Flues were visually inspected and checked for satisfactory evacuation of products of combustion. A detailed Name: This certificate was produced using The Master Gas internal inspection of the flue integrity, construction and lining has not been App. Copyright Gas Installers Workmate Ltd. Position: Landlord Date: 26 April 2022 carried out.